




Storage Trailer



Office Trailer

103 Kisco Avenue, Mount Kisco (C002)

<p>Legend</p> <p> - Radon/Thoron Survey Location - Exterior Wall - Interior Wall - Entry door </p> <p> OF - Office BR - Bathroom EC - Electrical Closet RL - Reception/Lobby LG - Lounge </p>	<p>Weston Solutions, Inc.</p> <p>In Association with Scientific and Environmental Associates, Inc., Environmental Consultants, Inc., Avatar Environmental, LLC, On-Site Environmental, Inc. and Sovereign Consulting, Inc.</p>	<p>Figure 4A: C002 Indoor Radon/Thoron (RAD7) Survey Map</p> <p>Canadian Radium and Uranium Site Mount. Kisco, New York</p> <p>U.S. ENVIRONMENTAL PROTECTION AGENCY Removal Support Team 3 CONTRACT # EP-S2-13-01</p>	
<p>Notes:</p> <p>Radon/thoron survey was conducted using Durrige RAD 7 radon/thoron detectors. Background radon (Ra)/thoron (Th) values = 0.0 - <4 picocuries per liter (pCi/L).</p>		<p>EPA OSC:</p> <p>RST SPM:</p> <p>PROJECT #:</p>	<p>E. DALY</p> <p>B. NWOSU</p> <p>30400.021.006.2053</p>